

**Deputy Commissioner Office, Mysuru District, Mysuru**  
**South West Monsoon-2023-24 - Daily Bulletin - dated – 26 July 2023**

Reservoir Details dated on 26 July 2023@ 8.30 A.M						Rainfall Pattern last 24 hrs Ending at 8.30A.M				
Sl. No	Dam Name	Max level of Dam (Feet)	Today's water level (Feet)	Inflow (Cusecs)	Out Flow (Cusecs)	Sl. no	MYSURU Dist CUMMULATIVE	Normal (mm)	Actual (mm)	%DEP
1	KRS dam	124.8 GL	104.80GL	51508	2853	A		3.3	7.3	121
2	Nugu	110 GL	103.00 GL	1615	0	Sl. No	Taluk Wise	Normal (mm)	Actual (mm)	%DEP
3	Kabini	2284 MSL	2281.86 MSL	26873	17396	1	H.D. Kote	3.2	11.6	263
4	Taraka	2425 MSL	2412.92 MSL	183	0	2	Hunsur	2.1	4.3	105
5	Harangi	2859 MSL	2853.13MSL	12861	12625	3	K.R. Nagara	2.1	6.0	186
						4	Saligram	2.5	9.4	275
						5	Mysuru	2.3	3.3	43
						6	Nanjanagud	2.1	6.0	186
						7	Periyapatna	2.8	10.7	282
						8	T.Narsipura	2.2	3.8	73
						9	Saraguru	2.6	12.3	373
<b>Rain Damages within 24 hrs If any</b>										
Sl. no	Name of Taluk	Human Loss	Injury	Big Animal Loss	Small animal Loss	Complete House Damage	Partial House damage	Agriculture Loss in Hectares	Horticulture Loss in Hectares	Any Infrastructure Damages
4	Periyapatna	Nil	Nil	Nil	Nil	Nil	05	Nil	Nil	Nil
5	Saligrama	Nil	Nil	Nil	Nil	Nil	04	Nil	Nil	Nil
Total		Nil	Nil	Nil	Nil	Nil	09	NIL	Nil	NIL
<b>Tankers and Hiring of Bore wells if any</b>										
Sl. no	Name of Taluk Rural supplied water through tankers	No of Tankers Hired	No of Bore wells	Name of the detailed ULBs Facing Drinking water Problems	No of Tankers	No of Bore wells				
1	Hunsuru taluk - Gurupura GP/ Nagapura village	01	Nil	Nil	Nil	Nil				